







STRIPPING DIMENSIONS

- NOTES:

 1. CABLE ATTACHMENT:

 1. OUTER: SOLDER.

 INNER: SOLDER.

 2. SPACER: LEAVE A GAP .020 [0.51]
 BETWEEN CONTACT AND CALBE.



THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNITED STATES IN ACCORDANCE WITH THE EXPORT

ADMINISTRATION REGULATIONS. DIVERSION CONTRARY TO U.S., LAW PROHIBITED.

IN THE SOFTHER DEFINITION FOR THE PROMET SOFTHER DEPORTED IN ADMINISTRATION SAFE INCHES



TITLE



X = ± 2 [5.08] XX = ± .005[.13] XXX = ± .005[.13] XXX = ± .005[.13]	UNLESS OTHE
X = ±.2 [5.08] FRACTIONS XX = ±.02 [.51] ± 1/32 XXX = ±.005[.13] ANGLES ± 1' ALL DIMENSIONS SHO ALL DIMENSIONS SHO ALL DIMENSIONS SHO ALL DIMENSIONS SHO	TWISH STECH
CABLE LEN 12 [305] < 1 60 [1524] < 1 120 [3048] < 1 30 WW ARE FOR RE DRAWN BY K DANG	ONLESS CHEERWISE SPECIFIED LEADING DIMENSIONS ARE INCHES
NCES: [25] / -0 [51] / -0 [102] / -0 [152] / -0 %L / -0 %MBER MBER	NS ARE INCHES
THE INFORMAT DESIGN IN THIS IS THE PROFE FAIRNER MICROWAVE ALL RIGHT'S RESULTED TO THE STATE OF	HRPANGLE FROMECTION
ION AND SOCIAMENT SOCIAMEN	7 5